



Photo 1. View of eastern portion of project area from northeastern corner facing southward. Sparse revegetation along the fill slopes.



Photo 2. View of northern portion of project area from northeastern corner facing westward.



Photo 3. View of southern portion of project area where it appears concentrated stormwater flows are carrying sediment outside of the project area.



Photo 4. View of western portion of project area from southwestern corner facing northward.



Photo 5. View of project area from northeastern corner facing center.