



Photo 1: Photo facing South, taken from access road at Sand Creek. Bare soil running left to right in photo is creek bottom. BMPs not installed on road.



Photo 2: Photo taken from cattle guard on access road, West of location facing East.



Photo 3: Photo taken from Southwest side of location looking East.



Photo 4: Photo taken from Southwest side of location facing North. Note insufficient storm water BMPs in place along West side of location.



Photo 5: Photo taken from South side of location facing South. Insufficient storm water BMPs in place.



Photo 6: Photo taken from Southeast side of location facing West.
Insufficient storm water BMPs in place.



Photo 7: Photo taken from Southeast side of Facing North. Note insufficient storm water BMPs in place.



Photo 8: Photo taken from Northeast side of location facing West. Note insufficient storm water BMPs in place along the North side of location.



Photo 9: Photo taken from Northwest side of location facing East. Note insufficient storm water BMPs in place along the North side of location.



Photo 10: Photo taken from Northwest of location looking South. Note insufficient storm water BMPs in place along the West side of location.