



Photo 1. View of project area from northeastern corner facing center. Short (less than 1 foot tall) kochia (*Kochia scoparia*) plants are the gray vegetation in the foreground, and rubber rabbitbrush (*Chrysothamnus nauseosus*) is the shrubby vegetation in the mid-ground.



Photo 2. View of eastern portion of the interim reclamation area from eastern edge facing southward. Sparse/poor revegetation here. Unused piping needs to be removed.



Photo 3. View of northern portion of the project area from northeastern corner facing westward. Poor revegetation here. A two-track crosses through the well pad through the northeastern corner (on right hand side of photo).



Photo 4. View of southern portion of project area from southeastern corner facing westward. Straw wattle is in disrepair, but vegetation and cobble on the slopes appear to be effectively reducing erosion.



Photo 5. View of western portion of the project area from the southwestern portion of the project area facing northward.