




Photo#1: Irrigation furrows for Gated Pipe system running from East to West where they meet edge of Location



Photo#2: Stabilized area West of access road..



Photo#3: End of Irrigated Field surrounding Location on NE border.



Photo#4: Point where Irrigation furrows meet Location Access road & drainage ditch