



Photo 1. Photo taken from northeast location, facing South. Stormwater control ditch in center of photo. Livestock (cattle) control fence installed around perimeter of disturbance.



Photo 2. Photo taken from northwest location, facing East. Stormwater control ditch in center of photo.



Photo 3. Photo taken from southwest location, facing North. Stormwater control ditch in center of photo.



Photo 4. Photo taken from southwest location, facing East. Stormwater control ditch in center of photo.



Photo 5. Photo taken from southeast location, facing North. Stormwater control ditch in center of photo.



Photo 6. Photo taken from eastern access entrance, facing Northeast. Cattle guard installed in center of photo.



Photo 7. Photo taken from southern location, facing North. Topsoil salvage in process.



Photo 8. Photo taken from southwest location, facing North. Topsoil salvage pile tracked perpendicular to slope.



Photo 9. Photo taken from southern location, facing Northwest. Topsoil salvage pile tracked perpendicular to slope.