



photo 1: West side of the location facing east.



photo 2: North side of the location. Metal panels remain.



photo 3: North side of the location. Metal panels remain.



photo 4: North side of the location. Metal panels remains off the well pad.



photo 5: East side of the location. Stormwater controls have been installed to prevent erosion.



photo 6: East side of the location facing west.



photo 7: Production equipment at the west side of the location.



photo 8: Pipe riser found at center of the location are not highly visible.