

**FORM
INSP**Rev
05/11**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

| DE | ET | OE | ES |
|----|----|----|----|
|----|----|----|----|

Inspection Date:
11/12/2015Document Number:
682500094Overall Inspection:
SATISFACTORY**FIELD INSPECTION FORM**

| | | | | | |
|---------------------|-------------|--------|-----------------|--------------------------|-------------|
| Location Identifier | Facility ID | Loc ID | Inspector Name: | On-Site Inspection | 2A Doc Num: |
| | 443451 | 443451 | Trujillo, Aaron | <input type="checkbox"/> | |

Operator Information:OGCC Operator Number: 96340Name of Operator: WIEPKING-FULLERTON ENERGY LLCAddress: 4600 S DOWNING STCity: ENGLEWOOD State: CO Zip: 80113

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED
- ☐ INSPECTOR REQUESTS FORM 42 WHEN CORRECTIVE ACTIONS ARE COMPLETED

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|----------------|--------------------------|-----------------|
| Boone, Linda | | LDBoonePar@aol.com | all inspections |
| Fincham, Jack | | fincham4@msn.com | all inspections |
| Weipking, Jeff | (303) 789-1798 | jwiepking@msn.com | All Inspections |
| Halde, Kerry | (719) 340-0329 | haldesand@centurytel.net | All Inspections |

Compliance Summary:QtrQtr: SWSW Sec: 16 Twp: 10S Range: 55W**Inspector Comment:**This is a follow-up, stormwater construction inspection.**Related Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status | |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|-------------------------------------|
| 443455 | WELL | DG | 10/26/2015 | | 073-06709 | Good Deal # 13 | DG | <input checked="" type="checkbox"/> |

Equipment:Location Inventory

| | | | |
|---------------------------------------|----------------------------------|-------------------------------|-----------------------------------|
| Special Purpose Pits: <u> </u> | Drilling Pits: <u>1</u> | Wells: <u>1</u> | Production Pits: <u> </u> |
| Condensate Tanks: <u> </u> | Water Tanks: <u>1</u> | Separators: <u>1</u> | Electric Motors: <u> </u> |
| Gas or Diesel Motors: <u> </u> | Cavity Pumps: <u> </u> | LACT Unit: <u> </u> | Pump Jacks: <u>1</u> |
| Electric Generators: <u> </u> | Gas Pipeline: <u> </u> | Oil Pipeline: <u> </u> | Water Pipeline: <u> </u> |
| Gas Compressors: <u> </u> | VOC Combustor: <u>1</u> | Oil Tanks: <u>1</u> | Dehydrator Units: <u> </u> |
| Multi-Well Pits: <u> </u> | Pigging Station: <u> </u> | Flare: <u> </u> | Fuel Tanks: <u> </u> |

LocationEmergency Contact Number (S/A/V): Corrective Date: Comment: Corrective Action: **Spills:**

| Type | Area | Volume | Corrective action | CA Date |
|------|------|--------|-------------------|---------|
|------|------|--------|-------------------|---------|

Inspector Name: Trujillo, Aaron

☐ Multiple Spills and Releases?

Venting:

Yes/No

Comment

Flaring:

Type

Satisfactory/Action Required

Comment

Corrective Action

CA Date

Predrill

Location ID: 443451

Site Preparation:

Lease Road Adeq.: _____

Pads: _____

Soil Stockpile: _____

S/A/V: _____

Corrective Action: _____ Date: _____ CDP Num.: _____

Form 2A COAs:

| Group | User | Comment | Date |
|-------|---------|---|------------|
| OGLA | HouseyM | Loxcaton lies within close proximity to Sand Creek. Operator shall implement tertiary containment along the cross- and downgradient perimeters of the Location. | 09/21/2015 |
| OGLA | HouseyM | Based on NRCS Map Unit Description, Haverson loam form on Floodplains. Although FIRM Maps for much of Lincoln County are not available, Location may be considered to lie within a potential floodplain based on proximity and geomorphic setting in conjunction with the soil description. Operator shall be in compliance with Rule 603.h. | 09/21/2015 |
| OGLA | HouseyM | Operator shall provide notice to COGCC 48 hours prior to commencing construction of this Oil and Gas Location via Form 42. | 09/21/2015 |

S/A/V: _____ **Comment:** _____

CA: _____ **Date:** _____

Wildlife BMPs:

| BMP Type | Comment |
|-----------------------------|--|
| Storm Water/Erosion Control | <p>BMP Plan</p> <p>Wiepking-Fullerton Energy, L.L.C. 4600 S. Downing St. Englewood, CO 80113 303-789-1798 303-761-9067 (fax)</p> <p>Certification to Discharge Under CDPS General Permit COR-03000 Stormwater Discharges Associated with Construction</p> <p>Certification Number COR 39788</p> <p>Good Deal # 13 well T10S, R55W Sec. 16: SW1/4SW1/4 Lincoln County, Colorado</p> <p>Description of Well Site and Construction Area 1-3 acre site with access road for drilling of oil and gas well. Terrain is flat with native grass and sagebrush. Surface water area Sand Creek, which is dry, located 450' west of well stake. Man-made pond located 150' south of well stake. Both areas will not be disturbed by drilling operations. Dirt berm will be installed on the west and south sides of well pad to protect this area. Surface Roughening will be used on low side of drill site to reduce speed of runoff, increase infiltration, reduce erosion, trap sediment and prepare soil for reseeding. Dig Mud Pit 6' deep with 30 mil liner which will be removed after drilling operations and pit reclaimed. No Water pit. Operator will use approved E & P Waste Management Plan to have all water based mud and cutting trucked to adjacent well. Topsoil will be separated and spread on drill site as final operation before reseeding operations. To prevent soil erosion site will be disked and straw crimped in or manure spread. Reclamation will begin within 6 months weather permitting</p> <p>Stormwater Management Plan (SWMP) is on file in Wiepking-Fullerton Energy, L.L.C. office.</p> <p>Spill Prevention, Control and Countermeasure Plan are on file in Wiepking-Fullerton Energy, L.L.C. office.</p> |

S/AV: _____ **Comment:** _____

CA: _____ **Date:** _____

Stormwater:

Comment: _____

Staking: _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____

Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____

Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Inspector Name: Trujillo, Aaron

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Facility

Facility ID: 443455 Type: WELL API Number: 073-06709 Status: DG Insp. Status: DG

Environmental

Spills/Releases:

Type of Spill: Description: Estimated Spill Volume:
Comment:
Corrective Action: Date:
Reportable: GPS: Lat Long
Proximity to Surface Water: Depth to Ground Water:

Water Well:

DWR Receipt Num: Owner Name: GPS : Lat Long

Field Parameters:

Sample Location:

Emission Control Burner (ECB):

Comment:

Pilot: Wildlife Protection Devices (fired vessels):

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: Date Interim Reclamation Completed:

Land Use: RANGELAND

Comment:

1003a. Debris removed? CM
CA CA Date
Waste Material Onsite? CM
CA CA Date
Unused or unneeded equipment onsite? CM
CA CA Date
Pit, cellars, rat holes and other bores closed? CM
CA CA Date
Guy line anchors removed? CM
CA CA Date
Guy line anchors marked? CM

CA _____

CA Date _____

1003b. Area no longer in use? _____

Production areas stabilized? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____

Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____

Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____

Recontoured _____

Perennial forage re-established _____

Non-Cropland

Top soil replaced _____

Recontoured _____

80% Revegetation _____

1003 f. Weeds Noxious weeds? _____

Comment: _____

Overall Interim Reclamation _____

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____

Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment: _____

Well plugged _____

Pit mouse/rat holes, cellars backfilled _____

Debris removed _____

No disturbance /Location never built _____

Access Roads Regraded _____

Contoured _____

Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____

Locations, facilities, roads, recontoured _____

Compaction alleviation _____

Dust and erosion control _____

Non cropland: Revegetated 80% _____

Cropland: perennial forage _____

Weeds present _____

Subsidence _____

Comment: _____

Corrective Action: _____

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches | Pass | | | | | |
| Berms | Pass | | | | | |
| Waddles | Pass | | | | | |

Inspector Name: Trujillo, Aaron

S/A/V: SATISFACTOR

Corrective Date: _____

Y

Comment: Adequate stormwater BMPs in place.

CA: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|------------|------------|
| Ensure stormwater BMPs are in place prior to construction activities. | trujilloam | 11/13/2015 |
| Adequate stormwater BMPs in place, see attached photos. | trujilloam | 11/13/2015 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|------------------------------|---|
| 682500095 | Construction Followup photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=3721093 |