

Inspection #66930086

COGCC Inspection Photographs: 30<sup>th</sup> September, 2015

EE3 LLC Photographs: 26<sup>th</sup> October, 2015



It is observed that low point is approximately 8-10" above pad surface.



Berms have been raised and compacted.



It is observed that low point is approximately 8-10" above pad surface.  
Note: No labels on tanks.



Berms have been raised and compacted. Missing tank labels have been applied.

**COGCC Inspection Photographs: 30th September, 2015**



Spill below hammer union

**EE3 LLC Photographs: 26th October, 2015**



Contaminated material has been removed and new gravel spread.



Discoloration of gravel on north side of tank battery



Contaminated material has been removed and new gravel spread.

**COGCC Inspection Photographs: 30th September, 2015**



Spill below hammer union

**EE3 LLC Photographs: 26th October, 2015**



Contaminated material has been removed and new gravel spread.



Liner day lighting on Westside of location



Berm has been raised and liner secured.

Inspection #66930086

COGCC Inspection Photographs: 30<sup>th</sup> September, 2015



Two tanks without NFPA diamond, (Rest of tanks contain diamond). Trash in foreground outside berm.

EE3 LLC Photographs: 26<sup>th</sup> October, 2015



All tanks now have NFPA diamonds. Trash / parts have been removed



Tank battery with low spots at loadouts visible.



Berms have been raised and compacted.



One enclosed flare, 1 unenclosed flare; both lit.



Unenclosed flare is no longer used, all gas is flared in enclosed flare.



Topsoil pile on south side of location with no visible protection or preservation.



Topsoil has been compacted



Topsoil pile on west side of location with o visible protection or preservation.



Topsoil has been compacted



**COAs have been implemented.**

COA #5 – Install raptor perch deterrents on equipment, fences, cross arms and pole tops in greater sage grouse habitat.

Raptor perch deterrents have been installed.