



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of straw mulch and revegetation within the interim reclamation area. Revegetation appears to be comprised of a cover crop of annual wheatgrass (*Triticum* sp.) and perennial grasses (not yet identifiable).



Photo 3. View of the western portion of the project area facing northward. Straw wattles are in place along the stormwater diversion channel and revegetation is progressing.



Photo 4. View of cobble lined silt trap and wattles appear to be in good condition within the southwestern corner of the project area.



Photo 5. View of northern portion of the project area from the northwest edge of the working area facing eastward.