

Stormwater and Construction Inspection

12/10/2015

Operator: Edge Energy LLC

Location ID: 443962

Weld County, CO

Section 18 T4S R62W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from access road. Photo of location sign.



Figure 2: Photo taken from access road facing west towards location.



Figure 3: Photo taken from southeast end of location, facing north. Photo of topsoil berm.



Figure 4: Photo taken from topsoil berm on east end of location, facing south. Photo shows insufficient stormwater BMPs in place.



Figure 5: Photo taken from topsoil berm on east end of location, facing northwest. Photo shows insufficient stormwater BMPs in place.



Figure 6: Photo taken from east end of location, facing south. Photo shows insufficient stormwater BMPs in place.



Figure 7: Photo taken at east end of location, facing north. Photo of stormwater BMP.



Figure 8: Photo taken at northeast end of location, facing north. Photo shows insufficient stormwater BMPs. Please note irrigation ditch on right of photo.



Figure 9: Photo taken from northeast end of location, facing south. Photo shows insufficient stormwater BMPs. Please note irrigation ditch on left of photo.



Figure 10: Photo taken from northeast end of location, facing west. Photo shows insufficient stormwater BMPs.



Figure 11: Photo taken from north end of location, facing east. Photo shows insufficient stormwater BMPs.



Figure 12: Photo taken from northwest end of location, facing east.



Figure 13: Photo taken from northwest end of location, facing south.



Figure 14: Photo taken from the southwest end of location, facing north.



Figure 15: Photo taken from the southwest end of location, facing east.