



photo 1: Facing north along former access road towards the location.



photo 2: Facing northwest along former access road towards the location.



photo 3: Soils along the former access road were compacted.



photo 4: Facing northwest towards the location. Erosion occurring where soils were ripped.



Photo 5: Southeast corner of location facing west. Weed debris is piling up along the fence line.



Photo 6: Southeast corner of location facing northwest.



Photo 7: Erosion channel beginning to develop near the center of the location.



Photo 8: Facing northwest near the center of the location. There was no vegetation establishment at this area.



Photo 9: Center of the location facing north.



photo 10: Center of the location facing west.



photo 11: Center of the location facing south.



photo 12: Center of the location facing east



photo 13: Facing south east towards the west side of the location.



photo 14: West side of the location facing southeast.