



photo 1: Facing east along former access road towards the location.



photo 2: Erosion occurring along the access road.



photo 3: Facing east towards the location.



photo 4: West side of the location facing east.



Photo 5: West side of the location facing northeast.



Photo 6: North side of the location facing southeast.



Photo 7: Weed debris (russian thistle) along the north side of the location.



Photo 8: North side of the location facing east.



Photo 9: Center of the location facing north.



photo 10: Center of the location facing west.



photo 11: Center of the location facing south.



photo 12: Center of the location facing east



photo 13: Near the center of the location facing east. This area has no vegetation establishment..



photo 14: Surrounding vegetation.