



Photo 1. Photo taken from southwestern corner, facing East. Stormwater BMP installed prior to construction of well pad (highlighted in red). Surface roughening is a temporary BMP and should be used in conjunction with other BMPs.



Photo 2. Photo taken from southwestern corner, facing North. Stormwater BMP installed prior to construction of well pad (highlighted in red). Surface roughening is a temporary BMP and should be used in conjunction with other BMPs.



Photo 3. Photo taken from northwestern corner, facing East. Stormwater BMP installed prior to construction of well pad (highlighted in red). Surface roughening is a temporary BMP and should be used in conjunction with other BMPs.



Photo 4. Photo taken from northeast corner, facing South. Stormwater BMP installed prior to construction of well pad (highlighted in red). Surface roughening is a temporary BMP and should be used in conjunction with other BMPs.



Photo 5. Photo taken from southeast corner, facing West. Stormwater BMP installed prior to construction of well pad (highlighted in red). Surface roughening is a temporary BMP and should be used in conjunction with other BMPs.



Photo 6. Photo taken from southeast corner, facing West. Topsoil salvage in process.