

Construction Inspection



Photo 1. Photo taken from entrance of location, facing West. Lease road BMPs installed and tracking devices.

Construction Inspection



Photo 2. Photo taken from eastern location, facing South. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 3. Photo taken from southeast location, facing West. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 4. Photo taken from southwest location, facing North. Stormwater BMP installed in center of photo. DO NOT scrape sediment into stormwater ditches. Stormwater ditches need to be maintained.

Construction Inspection



Photo 5. Photo taken from western location, facing North. Stormwater BMP installed in center of photo. DO NOT pile other soil material onto topsoil stockpile. Need to remove soil pile from topsoil stockpile.

Construction Inspection



Photo 6. Photo taken from northwest location, facing East. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 7. Photo taken from northern location, facing West. Stormwater BMP installed in center of photo. DO NOT scrape sediment into stormwater ditches. Stormwater ditches need to be maintained.