

Construction Inspection



Photo 1. Photo taken from southwest location, facing North. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 2. Photo taken from northwest location, facing North. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 3. Photo taken from northwest location, facing East. Stormwater BMP installed in center of photo and topsoil salvage stockpile.

Construction Inspection



Photo 4. Photo taken from northeast location, facing South. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 5. Photo taken from southeast location, facing West. Stormwater BMP installed in center of photo.