

Interim Reclamation Inspection



Photo 1. Photo taken of well signs for PR wells- API: 123-31909 and 123-31974.

Interim Reclamation Inspection



Photo 2. Photo taken from eastern location, facing South. Perimeter of well location being mowed to control undesirable plant species (*Kochia* sp. and Russian thistle).

Interim Reclamation Inspection



Photo 3. Photo taken from eastern location, facing North. Perimeter of well location being mowed to control undesirable plant species (*Kochia* sp. and Russian thistle).

Interim Reclamation Inspection



Photo 4. Photo taken from western location, facing South. Perimeter of well location being mowed to control undesirable plant species (*Kochia* sp. and Russian thistle).

Interim Reclamation Inspection



Photo 5. Photo taken from northern location, facing West. Portions of this location lack perennial vegetative growth as shown in the center of the photo.

Interim Reclamation Inspection



Photo 6. Photo taken from western location, facing Northeast. Portions of this location lack perennial vegetative growth as shown in the center of the photo.

Interim Reclamation Inspection



Photo 7. Photo taken from northern location, facing North. Portions of this location lack perennial vegetative growth as shown in the center of the photo.

Interim Reclamation Inspection



Photo 8. Reference photo taken west of location. Notice the uniform perennial vegetative growth.