



Photo#1: Overview of Location, to South .

January 2, 2016

Inspection Photos Loc# 336013,
Conductor?



Photo#2: Conductor Set no identification

January 2, 2016

Inspection Photos Loc# 336013,
Conductor?



Photo#3: Conductor Set close to C10 Well.

January 2, 2016

Inspection Photos Loc# 336013,
Conductor?