

Construction Inspection



Photo 1. Photo taken from the southwest location, facing East. Stormwater BMPs need to be in place before construction starts.

Construction Inspection



Photo 2. Photo taken from the southern location, facing North. Topsoil salvage in process.

Construction Inspection



Photo 3. Photo taken from the northeast location, facing West. Stormwater BMPs need to be installed before construction starts.