

## Cover Data

Date: 1/6/2016 Inspected By: Arvan Costa

Location/Operator: API # 073-06/52 Sundance Energy

[illegible]

2nd= second hit; P= plant species present but not hit





**photo 1:** Beginning of the vegetation transect facing west at the location.



**photo 2:** Ground view at the midpoint of the transect.





**photo 3:** Facing north at the midpoint of the transect.




**photo 4:** Facing south at the midpoint of the transect.





**photo 5:** End of the vegetation transect facing east at the location.



**photo 6:** Beginning of the vegetation transect facing north at reference area.





**photo 7:** Ground view at the midpoint of the transect.



**photo 8:** Facing east at the midpoint of the transect.





**photo 9:** Facing west at the midpoint of the transect.



**photo 10:** End of the vegetation transect facing south at the reference area.