

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

400968575

Date Received:

01/12/2016

Spill report taken by:

Spill/Release Point ID:

SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Any spill or release which may impact waters of the State must be reported as soon as practicable; any spill over 20 bbls must be reported within 24 hours and all spills over five bbls must be reported within ten days. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	Phone Numbers
Address: P O BOX 173779		Phone: (970) 336-3500
City: DENVER State: CO Zip: 80217-3779		Mobile: (970) 515-1238
Contact Person: Sam LaRue		Email: Sam.LaRue@anadarko.com

INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 400962248

Initial Report Date: 12/31/2015 Date of Discovery: 12/30/2015 Spill Type: Recent Spill

Spill/Release Point Location:

Location of Spill/Release: QTRQTR SWSW SEC 13 TWP 3N RNG 68W MERIDIAN 6

Latitude: 40.221656 Longitude: -104.956428

Municipality (if within municipal boundaries): County: WELD

Reference Location:

Facility Type: TANK BATTERY ☒ Facility/Location ID No 328410
☐ No Existing Facility or Location ID No.
☐ Well API No. (Only if the reference facility is well) 05- -

Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? No

Secondary containment, including walls & floor regardless of construction material, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? Yes

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): >=5 and <100

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): 0

Estimated Other E&P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

Land Use:

Current Land Use: NON-CROP LAND Other(Specify):

Weather Condition: 20 Degrees, Sunny

Surface Owner: FEE Other(Specify):

Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

On December 30, 2015, a release was discovered from a hole at the base of the oil tank at the PSC-63N68W production facility. It is estimated that approximately 10 barrels of oil were released within secondary containment. Site investigation activities are on-going and will be summarized in the forthcoming Supplemental Form 19.

List Agencies and Other Parties Notified:

OTHER NOTIFICATIONS

Date	Agency/Party	Contact	Phone	Response
12/30/2015	County	Roy Rudisill	-Email	
12/30/2015	County	Troy Swain	-Email	
12/30/2015	County	Tom Parko	-Email	
12/30/2015	Landowner	-	-Email	

SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 01/11/2016		
FLUIDS	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	10	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	0	0	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: _____			
Was spill/release completely contained within berms or secondary containment? <u>NO</u> Was an Emergency Pit constructed? <u>NO</u>			
Secondary containment, including walls & floor regardless of construction material , must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.			
A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): <u>22</u>		Width of Impact (feet): <u>25</u>	
Depth of Impact (feet BGS): <u>9</u>		Depth of Impact (inches BGS): <u>0</u>	
How was extent determined?			
On December 30, 2015, a release was discovered from a hole at the base of the oil tank at the PSC-63N68W production facility. It is estimated that approximately 10 barrels of oil were released. Excavation activities are on-going and are being guided in the field by screening soil for volatile organic compound (VOC) concentrations using a photoionization detector (PID). Approximately 160 cubic yards of impacted material have been excavated and transported to the Front Range Regional Landfill in Erie, Colorado for disposal. Confirmation soil samples will be collected from the final extent of the excavation area. Site investigation and excavation activities are on-going and will be summarized in subsequent Supplemental Form 19.			
Soil/Geology Description:			
Sand to sandy clay.			
Depth to Groundwater (feet BGS) <u>15</u>		Number Water Wells within 1/2 mile radius: <u>0</u>	
If less than 1 mile, distance in feet to nearest	Water Well <u>3365</u> None <input type="checkbox"/>	Surface Water <u>200</u> None <input type="checkbox"/>	
	Wetlands _____ None <input checked="" type="checkbox"/>	Springs _____ None <input checked="" type="checkbox"/>	
	Livestock _____ None <input checked="" type="checkbox"/>	Occupied Building <u>695</u> None <input type="checkbox"/>	

Additional Spill Details Not Provided Above:

CORRECTIVE ACTIONS

#1 Supplemental Report Date: 01/11/2016

Cause of Spill (Check all that apply) ☒ Human Error ☐ Equipment Failure ☐ Historical-Unknown

☐ Other (specify) _____

Describe Incident & Root Cause (include specific equipment and point of failure)

On December 30, 2015, an operator discovered a hole in the base of the oil tank. The hole appears to have been caused by a bullet.

Describe measures taken to prevent the problem(s) from reoccurring:

The above-ground storage tank will be replaced.

Volume of Soil Excavated (cubic yards): 160

Disposition of Excavated Soil (attach documentation) ☒ Offsite Disposal ☐ Onsite Treatment

☐ Other (specify) _____

Volume of Impacted Ground Water Removed (bbls): 0

Volume of Impacted Surface Water Removed (bbls): 0

REQUEST FOR CLOSURE

Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.

Basis for Closure: ☐ Corrective Actions Completed (documentation attached)

☐ Work proceeding under an approved Form 27

Form 27 Remediation Project No: _____

OPERATOR COMMENTS:

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: _____ Print Name: Sam LaRue

Title: Senior HSE Representative Date: 01/12/2016 Email: Sam.LaRue@anadarko.com

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

400968605	TOPOGRAPHIC MAP
400968606	FORM 19 SUBMITTED

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)