



Figure 1 - Becky #1 well sign.



Figure 2 - Becky #1 wellhead with small excavation.



Figure 3 - Localized soil staining inside of wellhead excavation.



Figure 4 - KPK Tank Battery sign.



Figure 5 - Well sign at tank battery.



Figure 6 - Paraffin buildup and stained soil beneath valve of north tank.



Figure 7 - Open excavation and compromised containment berms at SW corner of tank battery.



Figure 8 - Visible flowline inside of open excavation.



Figure 9 - View of excavation and compromised containment from south of tank battery.



Figure 10 - Horizontal separators, ECD, and partial fencing north of tank battery.