

Construction Inspection



Photo 1. Photo taken from entrance, facing East. Stormwater and sediment control BMPs installed before construction.

Construction Inspection



Photo 2. Photo taken from northern location, facing West. Stormwater and sediment control BMPs installed before construction.

Construction Inspection



Photo 3. Photo taken from northern location, facing East. Stormwater and sediment control BMPs installed before construction.

Construction Inspection



Photo 4. Photo taken from northeast location, facing South. Stormwater and sediment control BMPs installed before construction.

Construction Inspection



Photo 5. Photo taken from eastern location, facing South. Stormwater and sediment control BMPs installed before construction.

Construction Inspection



Photo 6. Photo taken from southern location, facing West. Stormwater and sediment control BMPs installed before construction.

Construction Inspection



Photo 7. Photo taken from southwest location, facing North. Stormwater and sediment control BMPs installed before construction.

Construction Inspection



Photo 8. Photo taken from southern location, facing North. Topsoil salvage in process. Need to stabilize topsoil stockpile upon completion of topsoil separation.