

Abandoned Location Inspection



Photo 1. Photo taken from center of location, facing West. It appears the location was never built.

Abandoned Location Inspection



Photo 2. Photo taken from center of location, facing North. It appears the location was never built.

Abandoned Location Inspection



Photo 3. Photo taken from center of location, facing East. It appears the location was never built.

Abandoned Location Inspection



Photo 4. Photo taken from center of location, facing South. It appears the location was never built.

Abandoned Location Inspection




Photo 5. Google Earth aerial photo taken 6/19/2014. It appears the location was never built based off aerial imagery and field observations.