

Construction Inspection



Photo 1. Photo taken from northwest location, facing South. Stormwater and sediment control BMPs installed along perimeter of location.

Construction Inspection



Photo 2. Photo taken from southeast location, facing North. Stormwater and sediment control BMPs installed along perimeter of location.

Construction Inspection



Photo 3. Photo taken from eastern location, facing Northeast. Stormwater and sediment control BMPs installed along perimeter of location.

Construction Inspection



Photo 4. Photo taken from northeast location, facing West. Stormwater and sediment control BMPs installed along perimeter of location. Topsoil stockpile needs to be stabilized upon completion of salvage operations.

Construction Inspection



Photo 5. Photo taken from eastern location, facing North. Topsoil stockpile located in center of photo. Topsoil stockpile needs to be stabilized upon completion of salvage operations.