

Interim Reclamation Inspection

2/9/2016

Operator: Whiting Oil and Gas

Location ID: 431632

Weld County, CO

SWSW Section 18 T10N R57W

Aaron Trujillo

Reclamation Specialist

COGCC



Figure 1: Photo taken from well head, facing east. Photo of well and sign.



Figure 2: Photo taken from access road south of location, facing north. Photo of location, interim area and stormwater controls.



Figure 3: Photo taken from access road south of location. Photo of stormwater control.



Figure 4: Photo taken from south end of location, facing north. Photo shows interim and project area.



Figure 5: Photo taken from southeast end of location, facing west. Photo shows vegetation on interim area. Eastern portions of interim area dominated by undesirable weedy vegetation.



Figure 6: Photo taken from east end of location. Photo shows vegetation on interim area. Eastern portions of interim area dominated by undesirable weedy vegetation.



02.09.2016 10:00

Figure 7: Photo taken from southeast end of location facing north. Photo shows project and interim areas.



Figure 8: Photo taken from east end of location, facing west. Photo shows vegetation on interim area. Eastern portions of interim area dominated by undesirable weedy vegetation.



Figure 9: Photo taken from northeast end of location, facing south. Photo shows interim and project area.



Figure 10: Photo taken from northeast end of location, facing west. Photo shows interim and project area.



Figure 11: Photo taken from north end of location, facing south. Photo shows vegetation on north end of interim area.



Figure 12: Photo taken from north end of location, facing south. Photo shows vegetation on north end of interim area.



Figure 13: Photo taken from northwest end of location, facing east. Photo shows interim and project areas.



Figure 14: Photo taken from northwest end of location, facing south. Photo shows interim and project areas.



Figure 15: Photo taken from northwest end of project area. Photo of erosion forming on berm.



Figure 16: Photo taken from northwest end of project area. Photo of erosion forming on berm.