

Interim Reclamation Inspection

2/9/2016

Operator: Whiting Oil and Gas

Location ID: 433919

Weld County, CO

NENE Section 21 T10N R58W

Aaron Trujillo

Reclamation Specialist

COGCC



Whiting Oil & Gas Corp
Block 21A-2815A
NE, NE, Sec 21, T10N, R58W
Well County, CO
API# - 051237847
Emergency # 1-800-723-4000

02.09.2016 12:34

Figure 1: Photo well sign at 123-37847.



Whiting Oil & Gas Corp
Razor 21A-2813A
NE 1/4, Sec 21, T10N, R56W
Weld County, CO
API# - 0512337848
Emergency # 1-800-723-4608

02.09.2016 12:35

Figure 2: Photo of sign at well 123-37848



 Whiting Oil & Gas Corp
Razor 21A-0916
NE, NE, Sec 21, T10N, R58W
Weld County, CO
API# - 0512339533
Emergency # 1-800-723-4608

02.09.2016 12:35

Figure 3: Photo of sign at well 123-39533



Figure 4: Photo of sign at 123-39530.



Figure 5: Photo of sign at 123-39528



Figure 6: Photo of sign at 123-39527



Figure 7: Photo taken from northwest end of location, facing south.



Figure 8: Photo taken from northwest end of location, facing east.



Figure 9: Photo of slope on west end of location. Soil appears to be drill cuttings.



Figure 10: Photo of stormwater ditch on west end of location.



Figure 11: Photo taken southwest end of location, facing east. Photo of drill cuttings stored on location, and stormwater waddles.



Figure 12: Photo taken southwest end of location, facing north. Photo of stormwater control berm.



Figure 13: Photo taken southwest end of location, facing east. Photo of drill cuttings stored on location, and stormwater berm.



Figure 14: Photo taken from southern end of location. Photo of what appears to be a tarp on project area.



Figure 15: Photo taken from southeast end of location, facing west. Photo of project area.



Figure 16: Photo taken from southeast end of location, facing north. Photo shows interim and project areas, and stormwater control berm.



Figure 17: Photo taken from east end of location on topsoil berm, facing north. Photo shows sparse desirable vegetation on interim area.



Figure 18: Photo taken from east end of location on topsoil berm, facing north. Photo shows sparse desirable vegetation on interim area.



Figure 19: Photo taken from east end of location on topsoil berm, facing south. Photo shows interim and project area.



Figure 20: Photo taken from east end of location on topsoil berm, facing west. Photo shows interim and project areas.