

## Construction Inspection



**Photo 1.** Photo taken from entrance of location, facing South. Tracking device installed to prevent sediment leaving location. Operator said gravel will be fluffed up to maintain proper functional use.

## A photograph showing a large, dark brown, textured mound of earth or sediment, possibly a dam or embankment, with patches of snow. In the background, there is a body of water, distant mountains, and industrial structures including a green building and silos. An orange timestamp '02.10.2016 16:07' is visible in the bottom right corner.

**Photo 2.** Photo taken from southeast location, facing West. Topsoil stockpile in center of photo and stormwater and sediment BMP along south-facing toe.

## Construction Inspection



**Photo 3.** Photo taken from southwest location, facing North. Topsoil stockpile in center of photo and stormwater and sediment BMP along west-facing toe.

## Construction Inspection



**Photo 4.** Photo taken from western location, facing North. Stormwater BMP installed along perimeter of location.

## Construction Inspection



**Photo 5.** Photo taken from northwest location, facing East. Stormwater BMP installed along perimeter of location. Need to stabilize topsoil stockpile and prevent soil leaving location. Operator said topsoil stockpile is in process of being moved from the western area to create space for operations.

## Construction Inspection



**Photo 6.** Photo taken from northeast location, facing South. Stormwater BMP installed along perimeter of location. Need to stabilize topsoil stockpile and prevent soil leaving location. Operator said topsoil stockpile is in process of being moved from the western area to create space for operations.

## Construction Inspection



**Photo 7.** Photo taken from northeast location, facing West. Need to stabilize topsoil stockpile and prevent soil leaving location. Operator said topsoil stockpile is in process of being moved from the western area to create space for operations.