

Interim Reclamation Inspection



Photo 1. Photo taken of Tank Battery location sign, facing South.

Interim Reclamation Inspection



Photo 2. Photo taken from northern location, facing Southeast. Need to remove weeds around all operating oil and gas equipment on location.

Interim Reclamation Inspection



Photo 3. Photo taken from southern location, facing Northeast. Need to remove weeds around all operating oil and gas equipment on location.

Interim Reclamation Inspection



Photo 4. Photo taken from pump jack, looking at the wellhead. Remove or remediate stained soil (<1 bbl) around wellhead.

Interim Reclamation Inspection



Photo 5. Photo taken from southern access road, facing East. Need to remove waste material from location.

Interim Reclamation Inspection



Photo 6. Photo taken from southern access road, facing East. Need to remove waste material from location.

Interim Reclamation Inspection



Photo 7. Photo taken along access road, facing North. Need to control noxious weeds (Bull thistle-*Cirsium vulgare*) along west access road.