

Interim Reclamation Inspection



Photo 1. Photo taken of well sign.

Interim Reclamation Inspection



Photo 2. Photo taken from central location, facing East. Need to remove weeds around all operating oil and gas equipment on location.

Interim Reclamation Inspection



Photo 3. Photo taken from southwest location, facing North. Need to remove weeds around all operating oil and gas equipment on location.

Interim Reclamation Inspection



Photo 4. Photo taken from southwest location, facing West. Need to remove weeds around all operating oil and gas equipment on location.

Interim Reclamation Inspection



Photo 5. Photo taken from central location, facing North. Need to remove weeds around all operating oil and gas equipment on location.

Interim Reclamation Inspection



Photo 6. Photo taken from central location, facing Southwest. Need to remove weeds around all operating oil and gas equipment on location.

Interim Reclamation Inspection



Photo 7. Photo taken from access road east of location, facing West. Appears to be noticeable erosion occurring along both sides of the access road ditch (see following photo).

Interim Reclamation Inspection



Photo 8. Photo taken from access road east of location, facing East. Appears to be noticeable erosion occurring along both sides of the access road ditch. Sediment traveling east, down slope towards the agricultural field.