

## Construction Inspection



**Photo 1.** Photo taken from western location, facing North. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 2.** Photo taken from southwestern location, facing East. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 3.** Photo taken from southwestern location, facing North. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 4.** Photo taken from southern location, facing Northeast. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 5.** Photo taken from southeast location, facing North. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 6.** Photo taken from northeast location, facing West. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 7.** Photo taken from northwest location, facing East. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 8.** Photo taken from northwest location, facing South. Stormwater and sediment control BMPs installed in center of photo.

## Construction Inspection



**Photo 9.** Photo taken from the southern location, facing North. Topsoil stockpile in center of photo.

## Construction Inspection



**Photo 10.** Photo taken from the eastern location, facing West. Topsoil stockpile in center of photo. Need to stabilize topsoil stockpile upon completion of topsoil salvage process.

## Construction Inspection



**Photo 11.** Photo taken from the southern location, facing Northeast. Topsoil salvage in process.

## Construction Inspection



**Photo 12.** Photo taken from the northern location, facing Northeast. Topsoil salvage in process.