

Interim Reclamation Inspection



Photo 1. Photo taken of PR well sign for API 123-13722.

Interim Reclamation Inspection



Photo 2. Photo taken from west of location, facing East. Remove weeds around wellhead. Weeds within 25 feet of operating oil and gas equipment are a potential safety or fire concern.

Interim Reclamation Inspection



Photo 3. Photo taken from south of location, facing North. Remove weeds around wellhead. Weeds within 25 feet of operating oil and gas equipment are a potential safety or fire concern.