



Photo#1: Overview of Location from reclaimed Access Road to NW

Photo#2:

Drainage flowing from North



Photo#3:

&

Into Location, view to SW





Photo#4:

Drainage Water flowing across Pad working its way to SE End of Location



Photo#5:



Photo#6:

Sediment migrating and Stormwater eroding channels at Southern Perimeter of Location



Photo#7:





Photo#8:

Portion of Water from Natural Drainage cuts around the NW corner, and channels to exit at NE corner of Location.

Photo#9



Photo#10:

Wattles need Maintenance

Photo#11:

