

Final Reclamation Inspection



Photo 1. Photo taken from entrance of location, facing North. It does not appear final reclamation has been conducted. Comply with Rule 1004- remove all surface equipment, abandoned gathering line risers and flowline risers, compaction alleviation, and revegetation.

Final Reclamation Inspection



Photo 2. Photo taken from northern location, facing South. It does not appear final reclamation has been conducted. Comply with Rule 1004- remove all surface equipment, abandoned gathering line risers and flowline risers, compaction alleviation, and revegetation.

Final Reclamation Inspection



Photo 3. Photo taken from northern location, facing East. It does not appear final reclamation has been conducted. Comply with Rule 1004- remove all surface equipment, abandoned gathering line risers and flowline risers, compaction alleviation, and revegetation.

Final Reclamation Inspection



Photo 4. Photo taken from northern location, facing South. Comply with Rule 1004- remove all surface equipment, abandoned gathering line risers and flowline risers, compaction alleviation, and revegetation.