

Inspection Photos
3/22/16
Facility #285505
BEARLY 24-29 ONSITE



Figure 1 – Lease sign.



Figure 2 – Wellhead and pit.



Figure 3 – Pipe to pit is currently disconnected.



Figure 4 – Piping from wellhead to pit. Metal pipe is disconnected.



Figure 5 – West side of pit.