

Inspection Photos  
3/28/16  
Facility #436580  
Aloha Mula #16 API 05-073-06590



Figure 1 – Lease sign.



Figure 2 – Looking from well pad to spill reclamation area.





Figure 3 – Reclaimed area.



Figure 4 – Reclaimed area and wellhead.