

ALL PHOTOS TAKEN 3/23/2016



Hatch that was the source of spill, “tee handles” on tank was not tight. Sandridge has adopted the procedure of truck drivers tightening the tee handles upon delivering the tanks, to prevent a similar spill in the future.



Back of tank that had spill.



Area behind frac tanks, soil appears that it could be drill cuttings. Operator should investigate the soil and determine proper disposition of soil.





Tank on left had contained spill in liner/secondary containment.



Secondary containment, has some residual water from cleaning the secondary containment.



Tank battery, under construction



