

## Interim Reclamation Inspection



**Photo 1.** Photo taken from Jacobucci 13, 23-32 tank battery, facing North. Need to remove trash per Rule 603.f.

## Interim Reclamation Inspection



**Photo 2.** Photo taken from Jacobucci 13, 23-32 tank battery, facing South. Need to maintain location to prevent vehicle tracking and rutting.

## Interim Reclamation Inspection



**Photo 3.** Photo taken from entrance of Jacobucci location, facing North. Need to maintain stormwater BMPs. Culvert is already half full.

## Interim Reclamation Inspection



**Photo 4.** Photo taken from northeast Jacobucci well location, facing West. Need to stabilize perimeter of pad.

## Interim Reclamation Inspection



**Photo 5.** Photo taken from northern Jacobucci well location, facing West. Need to stabilize perimeter of pad to prevent erosion off location.

## Interim Reclamation Inspection



**Photo 6.** Photo taken from northern Jacobucci well location, facing West. Need to stabilize perimeter of pad to prevent erosion off location.

## Interim Reclamation Inspection



**Photo 7.** Photo taken from northwest Jacobucci well location, facing West. Need to stabilize perimeter of pad to prevent erosion off location.

## Interim Reclamation Inspection



**Photo 8.** Photo taken from northwest Jacobucci well location, facing South. Need to stabilize perimeter of pad to prevent erosion off location.