

SSR 4-13

Inspection Doc# 675202719

Location on Previous
inspection 7/16/15



Location during current
inspection 4/19/16



Debris off location.
Identified on previous
inspection.



Waddles installed around
section of location.



Waddles installed without being trenched in. There is possible water and sediment movement underneath.



End of waddles, with no stormwater BMPs beyond this point.



Poly pipe is still off location with no BMPs around them and vegetation growing through it. Noted on previous inspections.



Area of erosion under poly pipe. Noted of previous inspections.



Barrel with no containment.



Area of erosion at the gate of the access road. Continued erosion may impede access to locations.