

## Final Reclamation Inspection- Abandoned Location



**Photo 1.** Photo taken from center of location, facing West. It appears the location was never built.



## Final Reclamation Inspection- Abandoned Location



**Photo 2.** Photo taken from center of location, facing North. It appears the location was never built.



## Final Reclamation Inspection- Abandoned Location



**Photo 3.** Photo taken from center of location, facing East. It appears the location was never built.



## Final Reclamation Inspection- Abandoned Location



**Photo 4.** Photo taken from center of location, facing South. It appears the location was never built.



## Final Reclamation Inspection- Abandoned Location



**Photo 5.** Google Earth aerial imagery taken 9/6/2013. It appears the location was never built based off aerial imagery and field observations.