



Photo 1. View of the southern portion of the project area from the well pad entrance facing eastward. Wire, cement, wood, etc. debris needs to be removed.



Photo 2. View of fencing debris in the southeastern corner of the project area that needs to be removed.





Photo 3. View of the northern portion of the project area from the northeastern corner facing westward. Vegetation in this area is comprised of rubber rabbitbrush (*Chrysothamnus nauseosus*), locoweed (*Astragalus* sp.), Indian ricegrass (*Achnatherum hymenoides*), field bindweed (*Convolvulus arvensis*), and crested wheatgrass (*Agropyron cristatum*).



Photo 4. View of the project area from the northeastern corner facing center.





Photo 5. View of the eastern portion of the project area from the northeastern corner facing southward.



Photo 6. View of the western portion of the project area from the northwestern corner facing southward.