



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern portion of the project area from the northeastern corner facing southward. No revegetation was observed on the majority of the eastern and northeastern cut-slope.





Photo 3. View of northern portion of the project area from the northeastern corner facing westward. Little revegetation on the cut-slope.



Photo 4. View of the western portion of the project area from the northwestern corner facing southward. Revegetation with perennial grasses appears to be progressing here. There are many weed seedlings of kochia (*Kochia scoparia*) and Russian thistle (*Salsola tragus*).





Photo 5. Birdseye view of vegetation within the western portion of the project area. Some perennial grasses are becoming established and a dense population of kochia is present.





Photo 6. View of erosion occurring along the edge of a wattle on the southwestern edge of the well pad.





Photo 7. View of wattle in the southwestern portion of the project area that needs maintenance.



Photo 8. View of the pipeline corridor that appears to have been recently seeded.





Photo 9. Birdseye view of vegetation within the pipeline tie corridor. Vegetation is largely cheatgrass (*Bromus tectorum*) with scattered perennial grasses that appear to be intermediate wheatgrass (*Thinopyron intermedium*).