



photo 1: Facing northwest at location.




photo 2: There is a dripping water leak from the well which was noticed in the previous inspection.



photo 3: Northwest side of the location facing south.



photo 4: Noticed Bull thistle beginning to germinate at the west side of the location.