

Final Reclamation Inspection



Photo 1. Photo taken from location entrance, facing South. Seeded and mulched along access road.

Final Reclamation Inspection



Photo 2. Photo taken from northern location, facing South. Seeded and mulched location.

Final Reclamation Inspection



Photo 3. Photo taken from northern location, facing Southeast. Seeded and mulched location. DCP equipment left behind.