

Final Reclamation Inspection



Photo 1. Photo taken from north of location, facing Southeast. It appears the location was never built.

Final Reclamation Inspection



Photo 2. Photo taken from north of location, facing South. It appears the location was never built.

Final Reclamation Inspection



Photo 3. Photo taken from north of location, facing Southwest. It appears the location was never built.

Final Reclamation Inspection




Photo 4. Google Earth aerial imagery taken 9/6/2013. It appears the location was never built based off aerial imagery and field observations.