

Final Reclamation Inspection



Photo 1. Google Earth aerial imagery taken 9/7/2013. Disturbance boundary highlighted in red is evident. Cut slopes still present and equipment left behind. See following photos.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing Northwest. Cut slope not stabilized with vegetation still in center of photo.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing North. This portion of the location is good vegetation establishment. Cattle trails are present throughout the location from current land use.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing East. This portion of the location is good vegetation establishment but cut slope sparsely vegetated.

Final Reclamation Inspection



Photo 5. Photo taken from center of location, facing South. This portion of the location lacks uniform vegetative plant cover and is dominated by cheatgrass (*Bromus tectorum*).

Final Reclamation Inspection



Photo 6. Photo taken from approximate location center. Equipment left behind.

Final Reclamation Inspection



Photo 7. Photo taken from approximate location center. Equipment left behind.

Final Reclamation Inspection



Photo 8. Photo taken from southern location, facing North. Cheatgrass throughout this portion of the location.