

Final Reclamation Inspection



Photo 1. COGCC GISOnline aerial imagery taken 09/2015. Location has been recently developed into some type of industrial land use. Refer to following photos.

Final Reclamation Inspection



Photo 2. Photo taken from center of location, facing West. Location has been recently developed into some type of industrial land use.

Final Reclamation Inspection



Photo 3. Photo taken from center of location, facing North. Location has been recently developed into some type of industrial land use.

Final Reclamation Inspection



Photo 4. Photo taken from center of location, facing East. Location has been recently developed into some type of industrial land use.

Final Reclamation Inspection



Photo 5. Photo taken from center of location, facing South. Location has been recently developed into some type of industrial land use.