

Construction Inspection



Photo 1. Photo taken from entrance of location, facing East. Culvert installed at entrance.

Construction Inspection



Photo 2. Photo taken from entrance of location, facing West. Culvert installed at entrance.

Construction Inspection



Photo 3. Photo taken from entrance of location, facing West. Second culvert installed along stormwater ditch.

Construction Inspection



Photo 4. Photo taken from southern location, facing East. Stormwater BMP installed in center of photo.

Construction Inspection



Photo 5. Photo taken from southeast location, facing South. Sediment trap being constructed.

Construction Inspection



Photo 6. Photo taken from southeast location, facing North. 2-sets of stormwater BMPs installed to control run-on from flood irrigation.

Construction Inspection



Photo 7. Photo taken from northeast location, facing West. 2-sets of stormwater BMPs installed to control run-on from flood irrigation.

Construction Inspection



Photo 8. Photo taken from northwest location, facing South. Stormwater BMPs installed in center of photo.

Construction Inspection



Photo 9. Photo taken from eastern location, facing West. Topsoil stockpile in center of photo. Topsoil stockpile needs to be stabilized upon completion of salvage process.