



Photo#1: Access Road into Location in process of reclamation.

June 2, 2016

Inspection Photos: OXY PA Cascade Creek Loc# 383339



Photo#2: De-compaction has occurred.

Inspection Photos: OXY PA Cascade Creek Loc# 383339

June 2, 2016





Photo#3: Steep Slopes will need monitoring to assess need for SW BMP's to stabilize Location until Vegetation establishes.

Inspection Photos: OXY PA Cascade Creek Loc# 383339

June 2, 2016