



Photo#1: Overview of Location to SW.



Photo#2: View of Location to NE.

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844

June 2, 2016



Photo#3:. View of Location Fill Slope to SW.

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844

June 2, 2016



Photo#4:. Areas of Fill Slope where material begins to slough and Channel Down Slope.

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844

June 2, 2016



Photo#5: Fill Slope on West side of Location; Material is rattling, migrating into Vegetation.

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844

June 2, 2016



Photo#6:. Vegetation is establishing on South and SW areas of Fill Slope.

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844

June 2, 2016



Photo#7: Deteriorated Blanket/netting has become Debris & could entangle Wildlife.

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844

June 2, 2016



Photo#8: Unstabilized Fill slope Material again moving into Vegetation & lack of effective BMP at base of Slope.

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844

June 2, 2016



Photo#9: Fill Slope at East side of Location Bellies out; accelerating movement of Material off Location.

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844

June 2, 2016



Photo#10: Aerial showing Areas no longer needed for foe Production or Use

June 2, 2016

Inspection Photos: Laramie Energy Cascade Creek Loc# 335844