

## Final Reclamation Inspection



**Photo 1.** Photo taken from center of location, facing West. No evidence of wellbore. Appears to have uniform growth throughout location area. No evidence of noxious weeds present.

## Final Reclamation Inspection



**Photo 2.** Photo taken from center of location, facing North. No evidence of wellbore. Appears to have uniform growth throughout location area. No evidence of noxious weeds present.

## Final Reclamation Inspection



**Photo 3.** Photo taken from center of location, facing East. No evidence of wellbore. Appears to have uniform growth throughout location area. No evidence of noxious weeds present.

## Final Reclamation Inspection



**Photo 4.** Photo taken from center of location, facing South. No evidence of wellbore. Appears to have uniform growth throughout location area. No evidence of noxious weeds present.

## Final Reclamation Inspection



**Photo 5.** Close-up photo taken from center of location.

## Final Reclamation Inspection



**Photo 6.** Reference photo taken southwest of location, facing East.

## Final Reclamation Inspection



**Photo 7.** Close-up reference photo illustrating comparable vegetative growth from the disturbed area in relation to the reference area